


PDB 10 Module- Quick Start Guide

Package Contents:

1* PDB 10 Module

Installation

- Input Power: Solder battery leads to input pads (Bat + and Bat -)
- ESC Connections: Solder ESC power leads (positive and ground) to the corresponding output pads (ESC+ and ESC-) Connect the ESC Control and Ground pin to the ESC
- Connect FMU and I/O PWM Outputs to corresponding ports in the Flight controller



Mounting Recommendation:

Secure the PDB using non-conductive standoffs or insulation spacers to prevent shorts.

Caution: Check polarity before soldering. Incorrect wiring can cause permanent damage.